

# 10 SPLINE QUICK CHANGE GEARS



Complete Quick Change, Transmissions, and Service parts also available



GEAR SET NO.	LOW SPUR RATIO	HIGH SPUR RATIO	NO. OF TEETH	4.11 AXLE RATIO (9-37 TEETH)		4.57 AXLE RATIO (7-32 TEETH)		4.86 AXLE RATIO (7-34 TEETH)	
				LOW	HIGH	LOW	HIGH	LOW	HIGH
1	1.00	1.00	21/21	4.11	4.11	4.57	4.57	4.86	4.86
2	0.96	1.03	27/28	3.96	4.26	4.41	4.71	4.68	5.04
5	0.96	1.04	24/25	3.95	4.28	4.39	4.75	4.66	5.07
15A	0.95	1.05	21/22	3.92	4.31	4.36	4.79	4.64	5.09
15	0.95	1.05	19/20	3.91	4.33	4.34	4.80	4.63	5.10
26	0.93	1.07	27/29	3.83	4.41	4.25	4.91	4.52	5.23
6	0.92	1.08	23/25	3.78	4.46	4.20	4.97	4.47	5.28
25	0.90	1.10	20/22	3.74	4.52	4.15	5.03	4.42	5.35
12	0.89	1.11	26/29	3.68	4.58	4.10	5.10	4.36	5.42
7	0.88	1.13	23/26	3.63	4.64	4.04	5.15	4.30	5.49
7A	0.87	1.14	21/24	3.58	4.69	4.00	5.22	4.23	5.54
17	0.86	1.15	26/30	3.54	4.76	3.96	5.27	4.19	5.64
17A	0.85	1.16	24/28	3.52	4.80	3.92	5.33	4.17	5.67
8A	0.85	1.17	23/27	3.50	4.82	3.89	5.36	4.14	5.71
8	0.84	1.18	22/26	3.48	4.85	3.87	5.40	4.11	5.75
19	0.84	1.19	21/25	3.45	4.89	3.84	5.44	4.08	5.78
9A	0.83	1.20	25/30	3.42	4.93	3.81	5.48	4.05	5.83
9	0.82	1.21	19/23	3.39	4.97	3.78	5.53	4.01	5.88
11	0.81	1.22	22/27	3.35	5.04	3.72	5.61	3.96	5.97
3	0.80	1.24	25/31	3.31	5.10	3.69	5.67	3.92	6.03
13	0.80	1.25	20/25	3.29	5.14	3.66	5.71	3.89	6.08
18	0.79	1.26	23/29	3.26	5.18	3.62	5.76	3.85	6.13
18A	0.79	1.27	22/28	3.23	5.23	3.59	5.82	3.82	6.19
4A	0.78	1.28	18/23	3.21	5.26	3.58	5.84	3.80	6.21
4	0.77	1.29	24/31	3.18	5.31	3.54	5.90	3.76	6.28
20	0.76	1.30	20/26	3.16	5.34	3.52	5.94	3.75	6.32
22	0.76	1.32	19/25	3.12	5.41	3.47	6.01	3.69	6.39
16	0.75	1.33	18/24	3.08	5.48	3.43	6.09	3.65	6.48
10	0.73	1.35	17/23	3.04	5.56	3.38	6.18	3.59	6.58
10A	0.73	1.36	22/30	3.01	5.60	3.35	6.23	3.56	6.63
34A	0.72	1.37	16/22	2.99	5.65	3.32	6.28	3.53	6.68
34	0.72	1.38	21/29	2.98	5.68	3.31	6.31	3.52	6.71
14	0.71	1.39	23/32	2.95	5.72	3.28	6.36	3.50	6.76
14A	0.71	1.40	20/28	2.93	5.76	3.26	6.40	3.47	6.81
35	0.70	1.41	17/24	2.91	5.80	3.24	6.45	3.44	6.86
32	0.70	1.42	19/27	2.89	5.85	3.22	6.49	3.42	6.90
32A	0.70	1.43	23/33	2.87	5.89	3.19	6.56	3.39	6.97
24	0.69	1.45	20/29	2.83	5.96	3.15	6.63	3.35	7.04
36	0.68	1.47	17/25	2.80	6.04	3.11	6.72	3.30	7.15
37	0.67	1.48	21/31	2.78	6.07	3.10	6.75	3.29	7.19
23	0.67	1.50	22/33	2.74	6.17	3.05	6.86	3.24	7.29
21	0.65	1.52	19/29	2.70	6.27	2.99	6.98	3.20	7.42
21A	0.65	1.53	15/23	2.68	6.30	2.98	7.01	3.17	7.45
27	0.64	1.54	22/34	2.66	6.35	2.96	7.06	3.15	7.52
43	0.64	1.56	16/25	2.63	6.42	2.92	7.14	3.11	7.59
28	0.63	1.57	19/30	2.60	6.49	2.89	7.22	3.08	7.68
28A	0.63	1.59	17/27	2.59	6.53	2.88	7.26	3.06	7.72
29	0.62	1.59	15/24	2.57	6.58	2.86	7.31	3.04	7.78
39	0.62	1.61	18/29	2.55	6.62	2.84	7.36	3.02	7.83
30	0.61	1.62	16/26	2.53	6.68	2.81	7.43	2.99	7.91
40	0.61	1.63	19/31	2.52	6.71	2.80	7.46	2.89	7.93
41	0.61	1.65	17/28	2.50	6.77	2.77	7.53	2.95	8.00
31	0.60	1.67	21/35	2.47	6.85	2.74	7.62	2.92	8.10
33A	0.59	1.69	16/27	2.44	6.94	2.71	7.71	2.88	8.20
33	0.58	1.70	20/34	2.42	6.99	2.69	7.77	2.85	8.26
31A	0.58	1.71	21/36	2.40	7.05	2.67	7.83	2.84	8.34
30A	0.57	1.73	15/26	2.37	7.12	2.64	7.92	2.80	8.42
<b>THE FOLLOWING NUMBERS ARE FOR LIMITED HORSEPOWER APPLICATIONS ONLY.</b>									
50	0.57	1.75	20/35	2.35	7.19	2.61	8.00	2.77	8.50
51	0.56	1.76	17/30	2.33	7.25	2.59	8.06	2.75	8.57
52	0.56	1.78	18/32	2.31	7.30	2.57	8.12	2.73	8.64
53	0.55	1.79	19/34	2.29	7.35	2.55	8.18	2.71	8.69
54	0.55	1.80	20/36	2.28	7.39	2.54	8.23	2.69	8.75
55	0.55	1.81	16/29	2.27	7.45	2.52	8.28	2.68	8.81
56	0.54	1.82	17/31	2.25	7.49	2.51	8.33	2.66	8.86
57	0.53	1.87	16/30	2.19	7.70	2.44	8.57	2.59	9.11
58	0.53	1.88	17/32	2.18	7.74	2.43	8.60	2.58	9.15

**RICHMOND**

SHIP • RELIABLE PARTS • DEPENDABLE SERVICE • QUALITY CRAFTSMANSHIP • RELIABLE PARTS • DEPENDABLE SERVICE

LEXINGTON MOORESVILLE  
**1(800)222-6805 • 1(800)615-6759**  
**FAX: 1(336)249-4922 • www.centralhp.com**

